

Classification:
 EC07-017a

Reference:
 ITB07-048a

Date:
 February 21, 2008

2008 G37; INTERMITTENT/SHORT DURATION SMALL RPM INCREASE DURING BRAKING

The bulletin has been amended. This version has a link to the CONSULT-III ECM Reprogramming General Procedure, addition of Applied VIN and addition of Applied Date. Please discard all copies of the earlier version.

APPLIED VEHICLE: 2008 G37 (CV36) with Automatic Transmission ONLY
APPLIED DATE: Built before December 6, 2007
APPLIED VIN: Built before JNKCV64E(*)8M 115669

IF YOU CONFIRM:

The engine intermittently experiences a small RPM increase (less than 500 RPM) for a short duration during braking.

ACTIONS:

1. Refer to Step 2 in the Service Procedure to confirm this bulletin applies to the vehicle you are working on.
2. If this bulletin applies; reprogram the ECM.

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reprogram ECM per TSB	(1)	DE98AA (2)	ZE	32	0.6 hrs (2)

- (1) Reference the Repair Order and use the current ECM P/N written down in Step 2 as the PFP.
- (2) FRT allows adequate time to access DTC codes and reprogram ECM. No other diagnostic procedures subsequently required – do NOT claim any Diagnostic Op Codes with this claim.

IMPORTANT: The purpose of "ACTIONS" (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure as it contains information that is essential to successfully completing this repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.