

Classification:
Reference:
Date:

FE08-002

ITB08-023

May 8, 2008

2008 G37; RATTLE IN MAIN MUFFLER

APPLIED VEHICLE: 2008 G37 (CV36)
APPLIED VIN: Vehicles built before JNKCV64E(*)8 120021
APPLIED DATE: Vehicles built before 29-Jan-2008

IF YOU CONFIRM:

There is a rattle sound coming from inside the main (rear) muffler assembly.

ACTION:

Replace the muffler assembly with the one listed in the Parts Information section of this bulletin.
 Reference the Electronic Service Manual for installation instructions.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Muffler Assy – Exhaust Main	20100-JL01B	1
Gasket – Exhaust	20692-1E810	2

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Main Muffler Assy	(1)	FD60AA	BC	32	(2)

- (1) Reference the Parts Information Table and use the Muffler Assy – Exhaust Main P/N as the PFP.
 (2) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.